



# QUICK RELEASE COUPLING KIT 58420

*Modified Couplers To Replace Original  
58796 and 58795*

[www.qtponline.com](http://www.qtponline.com)

Email

[info@qtponline.com](mailto:info@qtponline.com)

Telephone

00 353 44 934 1638

# REF QTP PART NUMBERS 59830, 58796 AND 58795 THE FOLLOWING PART NUMBERS HAVE BEEN DISCONTINUED.

**QTP PART NUMBER 59830 JD REF AL210585**

**QTP PART NUMBER 58796 JD REF AL210588**

**QTP PART NUMBER 58795 JD REF AL210587**

*These parts have been discontinued due to an OEM Upgrade.*

**When replacing the old coupler with the new version the following part numbers are needed.**

**QTP PART NUMBER 58422 JD REF L158630**

**QTP PART NUMBER 58421 JD REF AL218748**

**QTP PART NUMBER 58423 JD REF AL221083**

***To make replacement easier and a more cost effective solution  
QTP OFFERS A KIT 58420 with all 3 parts for fitment.***



# QUICK RELEASE COUPLING KIT 58420



## **To Maintain and increase the life of Hydraulic couplers the following points should be checked.**

- Inspect the hydraulic coupler including hose tip for damage or excessive wear.
- Debris can impact the coupling process remove all debris and clean thoroughly
- Replace damaged O rings or male coupler if required. Hose tip QTP Part No 1985
- Check hydraulic hoses are supported by the implement to prevent excessive loading of the coupler by the male coupler. Unsupported hoses may become uncoupled if not supported.
- Ensure that there is no unnecessary pressurised enforcement of the couplers

[www.qtponline.com](http://www.qtponline.com)

Email

[info@qtponline.com](mailto:info@qtponline.com)

Telephone

00 353 44 934 1638